





## Kit Masters Fan Clutches

Kit Masters fan clutches and rebuild kits are designed to solve common industry problems with innovative solutions.

Visit Website (https://kit-masters.com/)

Spanish Flyers (https://drive.google.com/drive/folders/1iJj4g5DtndbjuBPlq5aiHM2A1YoJghvn?usp=drive\_link)

Fan Clutches (https://kit-masters.com/fan-clutches/)

Spanish Contacts (https://drive.google.com/file/d/1JOTn9KqWVVSCJjpv6uGx0mn0yzslSe-6/view?usp=drive\_link)

Rebuild Kits (https://kit-masters.com/rebuild-kits/)

| Latin America Launch (https://drive.google.com/file/d/1ylJdHgsEO6pyPrChM0xbTY0Zpt8UlYAI/view?usp=drive_link)         |
|--|
| Fans (https://kit-masters.com/fans/)   |
| Controls (https://kit-masters.com/controls/)   |
| Belt Tensioners (https://kit-masters.com/polyforce/)   |
| Fleet ROI Calculator (https://kit-masters.com/fleetroi/)   |
| DTNA Part# Cross Reference (https://www.dtnapartscap.com/media/ujcbi4i3/dtna-part-interchange.xlsx)                  |
|  |
| Product Highlights   |
| Highest torque rating - Over 5,000 in/lbs of torque to handle nearly any size fan.                                   |
| Fail-safe design prevents on-the-road failures - Fan clutch automatically engages when it nears the end of its life. |
| Fewer individual components means less time to install.  |
| High quality internal components for long lifespan.  |

**Best Selling Products** 



# **BEST SELLING KITS & ACCESSORIES**

| OEM Part#        | OEM Brand    | Kit Masters Part# | DTNA Part#       | OEM Part#     | OEM Brand  | Kit Masters Part# | DTNA Part#      |
|------------------|--------------|-------------------|------------------|---------------|------------|-------------------|-----------------|
| 9908504          |              |                   |                  | Q995575       |            |                   |                 |
| 9908501          | Horton       |                   |                  | Q995568       | 1          |                   |                 |
| 9908500          |              |                   |                  | KQ795568      |            |                   |                 |
| 9908503          |              |                   |                  | 994347        |            |                   |                 |
| KYS1090-09600-01 |              |                   |                  | 994900        | 1          |                   |                 |
| KYS1090-09650-01 |              |                   |                  | 995530        | Horton     | 14-256            | KM N20 14256    |
| KYS1090-09500-01 |              |                   | 01N KM N20 8901N | 994985        |            |                   |                 |
| 1090-09500-01    |              |                   |                  | 995534        |            |                   |                 |
| 1090-09600-01    |              |                   |                  | 995567        |            |                   |                 |
| 1090-09650-01    | BorgWarner   |                   |                  | 995568        |            |                   |                 |
| 10900965001      |              |                   |                  | 995575        |            |                   |                 |
| 1090-08500-01    |              |                   |                  | Q995617       | Horton     | 24-256            | KM N20 24256    |
| 1090-09500-01B   |              | 8901N             |                  | Q995617-L     |            |                   |                 |
| 1090-09600-01B   |              |                   |                  | KQ795582      |            |                   |                 |
| 1090-09650-01B   |              |                   |                  | Q995582       |            |                   |                 |
| 2501022C91       |              |                   |                  | 995509        |            |                   |                 |
| 2509380C91       | No. total    |                   |                  | 995519        |            |                   |                 |
| 2514343C91       | Navistar     |                   |                  | 995557        |            |                   |                 |
| 2602141C91       |              |                   |                  | 995582        |            |                   |                 |
| 85108716         |              |                   |                  | 995624        |            |                   |                 |
| 85111808         | Mack Cummins |                   |                  | 995510        |            |                   |                 |
| 85134489         |              |                   |                  | 995518        |            |                   |                 |
| 3415013          |              |                   |                  | 995617        |            |                   |                 |
| 3915592          | Volvo        | Volvo             |                  | 995623        |            |                   |                 |
| f8hz-8a627-ua    | Ford         |                   |                  | 1033-07781-01 | BorgWarner |                   |                 |
| 1090-09900-01B   |              | BorgWarner 8905N  | KM N20 8905N     | 9908300       | Horton     | 8581-01           | KM N20 858101   |
| 1090-09750-01B   |              |                   |                  | 1695793C91    | Navistar   |                   |                 |
| 1090-09900-01    | Doroll/orner |                   |                  | Q995669       | Horton     | 14-256-1          | KM N20 142561   |
| 1090-09950-01B   | borgwarner   |                   |                  | 995031        |            |                   |                 |
| 1090-09750-01    |              |                   |                  | 995669        |            |                   |                 |
| 1090-09950-01    |              |                   |                  | KQ795669      |            |                   |                 |
| 9908504          | Horton       |                   |                  | 994353        |            |                   |                 |
| 994336           |              |                   | KM N20 9500HP    | 994902        | 1          |                   |                 |
| 994305           |              | 9500HP            |                  | 995511        | Horton     | 24-256-1          | KM N20 242561   |
| 994388           | Horton       |                   |                  | 995622        |            |                   |                 |
| 894305           | - Horton     |                   |                  | 995559        |            |                   |                 |
| 994389           |              |                   |                  | 995527        |            |                   |                 |
| 994322           |              |                   |                  | 2S-DP-S       |            |                   |                 |
|                  |              |                   |                  | Q995617-S     |            |                   |                 |
|                  |              |                   |                  | 994307        | Horton     | 7500HP            | KM N20 7500HP   |
|                  |              |                   |                  | 994324        | HOLOH      | 730011            | INVINZO / SOUTE |



## **BEST SELLING REMAN FAN CLUTCHES**



| Kit Masters Part# | DTNA Part#    | Kit Masters Part# | DTNA Part#   |
|-------------------|---------------|-------------------|--------------|
| 99782-2           | KM N20 997822 | 99103             | KM N20 99103 |
| 91024             | KM N20 91024  | 99495             | KM N20 99495 |
| 99334             | KM N20 99334  | 91010             | KM N20 91010 |
| 99223             | KM N20 99223  | 91007             | KM N20 91007 |
| 91014             | KM N20 91014  | 99067             | KM N20 99067 |
| 98621             | KM N20 98621  | 91009             | KM N20 91009 |
| 99346             | KM N20 99346  | 99552             | KM N20 99552 |
| 99897             | KM N20 99897  | 99142             | KM N20 99142 |
| 98652             | KM N20 98652  | 90007             | KM N20 90007 |
| 99649             | KM N20 99649  | 91019             | KM N20 91019 |

Specifications are subject to change without notice. Copyright © Daimler Truck North America LLC. All rights reserved.

DTNA Parts is a Daimler Truck North America brand.

### Part Number Interchange

**Download** the complete Kit Masters product line cross-reference.

### **Rep Contact List**

| National Sales Manager         | Kate Diecks                                      | kate@kitmasters.com                            | (412)660-7169  |
|--------------------------------|--|--|--|
| Western Regional Sales Manager | Adam Diecks                                      | adam@kitmasters.com                            | (412)849-5292  |
| Eastern Regional Sales Manager | Colby Dishmond                                   |  | (704)880-1947  |
| Sales Coordinator              | Lindsey Diecks                                   | colby@kitmasters.com<br>lindsey@kitmasters.com | (412)951-9132  |
| Sales/Owner                    | Brian Swanson                                    | brian@kitmasters.com                           | (651)338-9333  |
| Enders & Assoc                 | Email  | Phone  | Territory  |
| Don Gritzmacher (P)            | dgritzmacher@teamenders.com                      | (503)735-0115                                  | ,  |
| Logan Mayer                    | lmayer@teamenders.com                            | (253)802-2336                                  | WA, AK   |
| Reed Miller                    | rmiller@teamenders.com                           | (503)799-2702                                  | ID, OR   |
| Rob Orndorff                   | rorndorff@teamenders.com                         | (509)954-4405                                  | WA, ID, MT   |
| Miller & Assoc                 | Email  | Phone  | Territory  |
| Tom Miller (P)                 | tom@maalink.com                                  | (619)846-2213                                  |  |
| Jeff Owen                      | jeff@maalink.com                                 | (909)226-0552                                  | South CA   |
| Jason Miller                   | jason@maalink.com                                | (714)235-5278                                  | L.A. Metro   |
| Matt Furrey                    | matt@maalink.com                                 | (480)296-5237                                  | North CA, North NV, HI   |
| Nate Lewand                    | nate@maalink.com                                 | (978)790-1747                                  | WY, UT, CO   |
| Jeff "JT" Tinkle               | jt@maalink.com                                   | (480) 381-0267                                 | AZ, Northern NM  |
| Reese Company                  | Email  | Phone  | Territory  |
| Jon Reese (P)                  | reesecojr@outlook.com                            | (847)274-9970                                  | IL   |
| Chad Mecl (P)                  | chadmecl@me.com                                  | (651)249-8774                                  | MN, ND, SD   |
| Brad Hesse (P)                 | bradhesse@gmail.com                              | (847)274-5539                                  | WI   |
| MINK Marketing                 | Email  | Phone  | Territory  |
| Chris Seiwert (P)              | chris@mink-link.com                              | (316)680-1403                                  | KS LA NE MO  |
| Ryan Nelson (P)                | Ryan@mink-link.com                               | (816)589-9860                                  | IA, NE, MO   |
| Cree & Cree                    | Email  | Phone (214)850 7221                            | Territory  |
| Kyle Jones (P) Will Nees       | kjones@ccisales.com<br>wnees@ccisales.com        | (214)850-7331<br>(713)818-2941                 | Fleetpride Houston/San Antonio/Rio Grand Valley                  |
| Jimmie Edwards                 | jedwards@ccisales.com                            | (405)306-4495                                  | OK, West TX  |
| Mike McDaniel                  | mike@ccisales.com                                | (817)223-4403                                  | Forth Worth  |
| Jack Foster                    | ifoster@ccisales.com                             | (214)490-5093                                  | North TX   |
| Mike Flores                    | mflores@ccisales.com                             | (214)430-3033                                  | San Antonio Valley   |
| Triton HD Sales                | Email  | Phone  | Territory  |
| Chad Tyree                     | chad@tritonheavyduty.com                         |  | ,  |
| Phil Bruno (P)                 | phil@tritonheavyduty.com                         | (561)307-7808                                  | FL (Except Panhandle)  |
| Matt Tyree                     | matt@tritonheavyduty.com                         | (727)403-1933                                  | TN, North AL, North MS   |
| Ryan Lincoln                   | ryan@tritonheavyduty.com                         | (607)331-6141                                  | GA, South AL, South MS, FL Panhandle                             |
| Martha Mendoza                 | martha@tritonheavduty.com                        | 713-972-4492                                   | Sout LA  |
| Jon Cabino                     | jon@tritonheavyduty.com                          | (727)542-1022                                  | AR, North LA   |
| TW Sales                       | Email  | Phone (010) 633 0783                           | Territory  |
| Jack Wolan (P)<br>Ryan Joyce   | jwolan@sbcglobal.net<br>rjoyce.twsales@gmail.com | (810) 623-0783<br>(440) 477-9045               | MI, IN, Toledo, OH OH  |
| Dan Turner                     | danddc1298@aol.com                               | (419) 566-1450                                 | IN, KY, Southwest OH   |
| RP Schumann                    | Email  | Phone  | Territory  |
| Doug Lashley (P)               | doug@rpsheavyduty.com                            | (215)651-1846                                  | East PA, MD, North VA, South NJ, DE                              |
| Nate Lashley                   | nate@rpsheavyduty.com                            | (919)414-0471                                  | VA, South WV, NC, SC   |
| Jim Corey                      | jim@rpsheavyduty.com                             | (315)-755-8405                                 | Metro CT, Northern NJ, Northern WV, PA, NY, MA, NH, VT,ME and RI |
| Paul Schumann                  | paul@rpsheavyduty.com                            | (215)669-8353                                  | Central PA   |
| Amber Lashley                  | amber@rpsheavyduty.com                           | (302) 614-1778                                 | East Shore MD & DE   |
| James Corey Tim Schaffner      | james@rpsheavyduty.com<br>tim@rpsheavyduty.com   | (315) 980-4779<br>(717) 226-0671               | RI, CT, NJ, Long Island & Metro NY                               |
| Grant Brothers Sales           | Email  | Phone  | MD, DE, & Washington DC Area  Territory                          |
| Bob Bernard (P)                | Bob@gbsales.com                                  | (416)220-1370                                  | NB, NL, PE, NS, ON   |
| Adam Crisp (P)                 | acrisp@gbsales.com                               | (416)873-9678                                  | ,, 12, 10, 011   |
| Rene Levasseur                 | rene@gbsales.com                                 | (514) 601-5980                                 | QC   |
| Dean Lubchenko                 | d2@gbsales.com                                   | (587)341-0405                                  | AB, BC   |
| David Allen                    | dallan@gbsales.com                               | (204)333-2149                                  |  |
| Jerry Jazakos                  | jerry@gbsales.com                                | (416) 460-0665                                 | ON   |
| Kevin Ashdown                  | kevin@gbsales.com                                | (604) 831-7276                                 | BC SK MD Not a COM   |
| Norm Landreville               | norm@gbsales.com                                 | (204) 914-4194                                 | SK, MB, Nothern ON   |

#### **General Product Information**

The key reason for premature spring-engaged fan clutch failures is *lack of torque*. There are fan blades in operation today that require more torque than current fan clutches can produce. Our spring-engaged rebuild kit is unmatched by any competitors (new or re-manufactured) & packs over **5,000 inch-pounds of torque!** 

#### **Highest Torque Rating**

Sustaining fan blade engagement requires a large amount of torque. With over 5,000 inch-pounds of torque, our fan clutch will handle nearly all fan blades!

#### **Less Time To Install**

Our exclusive design combines nine separate components into **one final assembly** – this dramatically reduces installation time and installation errors.

#### Fail-Safe Design

Our innovative design will AUTOMATICALLY ENGAGE fan clutches when the friction material nears the end of its life.

### **Warranty Information**

300,000 mile/3 year warranty

Last updated: Tuesday, 07 October 2025 05:41 PM

**∧**Back to Top

Copyright © Daimler Truck North America LLC. <u>Privacy Statement, Legal Notices and Terms</u>
(<a href="https://northamerica.daimlertruck.com/privacy-policy">https://northamerica.daimlertruck.com/privacy-policy</a>). <u>Privacy Settings</u>
All rights reserved. Daimler Truck North America LLC is a Daimler company.